


BOOGER... IN THE PAN!

By Gary Elam

This is what happens after you replace a burnt valve, torque head down, then warm up the engine, and you do not re-torque it. I ended up with three burnt exhaust valves



Note from the Editor:
Special thanks to
Gary Elam
for this submission

